

VISIBLE EMISSION NOTA	TIONS			<del>-</del>	
Inspector:	Atom				
Date of Inspection: $3/1/2$			,		
Shift: 1 <sup>st</sup> Shift or 2 <sup>sd</sup> Sh	ift Th	me:500AM			
The first of the second of the	Visual Inspection <u>NOR</u> MAL or ABNORMAL		Comments		:
Visible Emission From Shaker	Nor	-	~		
Visible Emission From Discharge Conveyor System	Nox				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS			
Inspector:	4 ~			
1edC.				
Date of Inspection:	26			
Shift: 1 <sup>st</sup> Shift or 2 <sup>nd</sup> )Sh	lift Ti	me: 500 AM		
Unit	Visual		Comments	
	Inspection <u>NOR</u> MAL			
	or ABNORMAL			
Visible Emission From Shaker	$N_{o}$			
Visible Emission From				
Discharge Conveyor System	Na-			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS			•
Inspector: Ted Com	Rton		4	
Date of Inspection: 3/3//	٤.			
Shift: 1 <sup>st</sup> Shift or 2 <sup>nd</sup> Sh	ift Tir	me: 500AW)		
Junit	Visual Inspection <u>NOR</u> MAL or ABNORMAL		Comments	
Visible Emission From Shaker	Nar			
Visible Emission From Discharge Conveyor System	Nac			


- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Inspector:	
Date of Inspection:	
Shift: 1 <sup>st</sup> Shift or 2 <sup>nd</sup> Shift Time:	
Visual Inspection  NORMAL  or  ABNORMAL  Visible Emission From Shaker	Comments
Visible Emission From Discharge Conveyor System	

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Inspector:			
Date of Inspection:			
Shift: 1 <sup>st</sup> Shift or 2 <sup>nd</sup> Shift	Time:		
	Visual ispection NORMAL or BNORMAL	Comments	
Visible Emission From Discharge Conveyor System			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.



Inspector:	Mi	Torce	,	
Date of Inspection:	3/	4/17		
Shift: 1 <sup>st</sup> Shift or 2 <sup>nd</sup> Sh		me: 6:00c		
Unit	Visual Inspection <u>NØR</u> MAL or <u>ABN</u> ORMAL		Comments	
Visible Emission From Shaker	Noc	. The proposed specific specif	angganggan di saga	
Visible Emission From Discharge Conveyor System	Nov	Annuana		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS
Inspector:

Date of Inspection:

Shift: 1<sup>st</sup> Shift or 2<sup>nd</sup> Shift)

Time:

O 500

		0000		
ont.	Visual Inspection <u>NOR</u> MAL Or ABNORMAL		Comments	
Visible Emission From Shaker	Non			
Visible Emission From Discharge Conveyor System	No	Na.		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS			-
Inspector:	ompten			
Date of Inspection:	12"			
Shift: 1 <sup>st</sup> Shift or 2 <sup>hd</sup> Shi	lft Ti	me: 500 A M		
Design of the second second	Visual		Comments	
	Inspection NORMAL			
	or AB <u>N</u> ORMAL			
Visible Emission From Shaker	Nor			
Visible Emission From				
Discharge Conveyor System	Nov			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

١	/ISIBI			/IIC	SIC	147	NOT	' A T		IC
١	กอเยเ	-	F-1	งเเร	SIL	N	NOI	$\mathbf{A}$	ハ	1.7

Inspector:				
Date of Inspection:	3/8/12			
Shift: (1 <sup>st</sup> Shift) or 2 <sup>nd</sup> Sh		ime: (7:00		
Property Services	Visual Inspection <u>NOR</u> MAL Or ABNORMAL		Comments	
Visible Emission From Shaker	Now	_		
Visible Emission From Discharge Conveyor System	Nen	water		


- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS		-	·
Inspector:	1			
180,000	200		.,	
Date of Inspection:	2			
Shift: 1 <sup>st</sup> Shift or (2 <sup>po</sup> )Sh	ift Tir	me: SOOAM		
Unit	Visual		Comments	
	Inspection <u>NOR</u> MAL			
	<u>ABN</u> ORMAL			
Visible Emission From Shaker	Non			
Visible Emission From	1	· · · · · · · · · · · · · · · · · · ·		
Discharge Conveyor System	Nor	** The control of the Particle Annual Control of the Control of th	Squared SSP Instance of 1970 1 To 1 To 1	

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Inspector:	u.		_	
Date of Inspection:	Blake			
Shift: (1 <sup>st</sup> Shift or 2 <sup>na</sup> Sh	UI I I ICX	me: 🔘 👝		
31111.	11.	Me. (2) (7:00		
Unit	Visual Inspection <u>NOR</u> MAL or ABNORMAL		Comments	
Visible Emission From Shaker	Nal	· messanis.		
Visible Emission From Discharge Conveyor System	Non	Nagagarite.		·

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTA	TIONS		-	
Inspector:	ompton			
Date of Inspection:	12"		,	
Shift: 1 <sup>st</sup> Shift or (2 <sup>frd</sup> Shi	ft Ti	me: 500AM		
Unit	Visual Inspection <u>NOR</u> MAL or <u>ABN</u> ORMAL		Comments	
Visible Emission From Shaker	Nos			
Visible Emission From Discharge Conveyor System	Ner			_

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS			-
Inspector:				
			_	
Date of Inspection:	3/10/12			
	1100	<del></del>	_	
Shift: (1st Shift) or 2nd Sh	ift Ti	me: () ()		
		E (1;00		
- Juni	Visual		Comments	
<b>能震荡起来</b> 自己的第三人称形式	Inspection			
開発とは特殊を使うない。	<u>NOR</u> MAL			
	or <u>ABN</u> ORMAL			
CA HANTER RESTRICTION OF THE CO.	ABNORMAL	·	The second secon	·
Visible Emission From Shaker	Nal			
Í	200	. Commer		
Visible Emission From		Name:		
Discharge Conveyor System	Nac			•
	•			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Inspector:				
Date of Inspection:	3/11/12			
Shift: nst Shift or 2nd Sh	ift Ti	me: @17:00		
The second second	Visual Inspection <u>NOR</u> MAL or ABNORMAL		Comments	
Visible Emission From Shaker	Non	pulled in the second of the se		
Visible Emission From Discharge Conveyor System	Non			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS			
Inspector:	De la companya de la			
Date of Inspection:	3/12/12		,	
Shift: (1 <sup>st</sup> Shift) or 2 <sup>nd</sup> Sh	ift Ti	me: OPioo		
Unit.	Visual		Comments	
	Inspection <u>NOR</u> MAL or <u>ABN</u> ORMAL			
Visible Emission From Shaker	Don	_		
Visible Emission From Discharge Conveyor System	alar			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS			
Inspector:			•	
Date of Inspection:	2/2/2			
	2/13/12			
Shift: 1st Shift or 2nd Sh	ift Ti	me.		
		U1+100	•	
Unit	Visual Inspection		Comments	
	NORMAL			
	or <u>ABN</u> ORMAL			
Visible Emission From Shaker	Non	-		
Visible Emission From Discharge Conveyor System	Nor	_		
1	1 .			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS			-	
Inspector: Ted Com	of i				
Date of Inspection: 3/5/	2				
Shift: 1 <sup>st</sup> Shift or 2 <sup>nd</sup> Sh	lift Ti	me: 500 AM			
Unit	Visual		Comments		
	Inspection <u>NOR</u> MAL or				
Visible Emission From Shaker	ABNORMAL		<u> </u>		
Visible Emission Form Shaker	1100		erence :		
Visible Emission From	4				
Discharge Conveyor System	l N/				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.





VISIBLE EMISSION NOTA	TIONS				•	
Inspector:	· Lambouranger	3144				
Data of languages	5 00 1 0 00					
Date of Inspection: 3/6/	12			,		
Shift: 1 <sup>st</sup> Shift or (2 <sup>nd</sup> )Sh	lift Ti	me:				
Unit	Visual		Co	mments	• • • •	•
	Inspection					: :
	<u>NOR</u> MAL					
	or			The state of the s	•	, R
[2] [2] [2] [2] [2] [2] [2] [2] [2] [2]	<u>ABN</u> ORMAL			alama Kira	•	
Visible Emission From Shaker	Λ/	A CONTRACT OF THE PROPERTY AND ADDRESS OF THE STATE OF TH				
	1400	3 Marin Callant (Callant)				
Visible Emission From						
Discharge Conveyor System	A /	+NNMFW_22eprococks-provide_coc				
_ ,	1000	200 Control (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990) (1990)				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Inspector:				
Date of Inspection:	* ,			
Shift: 1 <sup>st</sup> Shift or 2 <sup>nd</sup> Sh	ift Ti	me:		
Dinit	Visual Inspection NORMAL Or ABNORMAL		Comments	
Visible Emission From Shaker				
Visible Emission From Discharge Conveyor System				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS			-
Inspector: RICK PA	+Lono		,,	
Date of Inspection: 3/19	1/iz			
Shift: 1 <sup>st</sup> Shift or 2 <sup>nd</sup> Sh	74	me: 5.00 AM		
Umt	Visual		Comments	
	Inspection <u>NOR</u> MAL or			
[1] [1] [1] [1] [1] [1] [1] [1] [1] [1]	ABNORMAL			·
Visible Emission From Shaker	NOR	. and the primary community of the country of the c		
Visible Emission From Discharge Conveyor System	NOR	and the second s		

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS			
Inspector:				
	MPTON	<u> </u>	0	
Date of Inspection: 3/20/13	<i>∀</i> ,			
Shift: 1 <sup>st</sup> Shift or (2 <sup>na</sup> )Sh	ift Ti	e: 5:00 AM		
Unit	Visual	in e a novembro governo de la compansión 🕻	omments	
	Inspection			
	<u>NOR</u> MAL			
	or		randia Matridia. Malaysia san	
	ABNORMAL		The Open Control of the Control of t	
Visible Emission From Shaker	Nor			
Visible Emission From				
Discharge Conveyor System	A I			
j , , , , , , , , , , , , , , , , , , ,	N/a/			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS					-	
Inspector:	- Santa						
169 6	MOTEN			•			
Date of Inspection:	الله الله الله الله الله الله الله الله			. •			
Shift: 1 <sup>st</sup> Shift or 2 <sup>nd</sup> Shi	ft Tir	me: 500 A n	n		•		
La de la Companya de	Visual			Comments			•
	Inspection	1					1 :
	<u>NOR</u> MAL						
	or AB <u>N</u> ORMAL			Training of			· · · · · · · · · · · · · · · · · · ·
Visible Emission From Shaker	No		and the state of t				14
Visible Emission From	1 7 11 7						
Discharge Conveyor System	Nor	g and the second	and the state of t				

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS			•	
Inspector:	ompton				
Date of Inspection: 3/23	lit				
Shift: 1 <sup>st</sup> Shift or 2 <sup>nd</sup> Sh	ifft Ti	me: 500 AM			
The sunit	Visual		Comments		
	Inspection <u>NOR</u> MAL or <u>ABNORMAL</u>				
VIsible Emission From Shaker	Nor	Party mental de como como a mane de presidente a manera de presidente de construcción de const			
Visible Emission From					
Discharge Conveyor System	Nov	_acceptioneedshiftillitiesseeneedstinee.			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS		_	
Inspector:	nten		,	
Date of Inspection: 3/26/	1 \$\sqrt{2}'		,	
Shift: 1 <sup>st</sup> Shift or (2 <sup>nd</sup> )Sh	lft Ti	me: 500 A M		
Entre Service Control Control	Visual		Comments	
	Inspection <u>NOR</u> MAL or <u>ABN</u> ORMAL			
Visible Emission From Shaker	Nor	\$2000 galangaranan ditarih retaran sagan sag		
Visible Emission From Discharge Conveyor System	Nor			

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

AIRIPE FINISSION NOTA	TIONS /				•	
Inspector:	where	)				
Date of Inspection: 3/28/	12					
Shift: 1 <sup>st</sup> Shift or 2 <sup>nd</sup> Sh	ılft Ti	me: 500 A V				
THE STATE OF THE S	Visual		Cor	mments		
	inspection <u>NOR</u> MAL or: ABNORMAL				• : • • •	
Visible Emission From Shaker	Nor	**************************************				
Visible Emission From Discharge Conveyor System	Nor					

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTA	TIONS			
Inspector:	nton			
Date of Inspection:	112			
Shift: 1 <sup>st</sup> Shift or 2 <sup>nd</sup> Sh	ılft Ti	me: 500 AM		
Light the punt	Visual		Comments	•
	Inspection <u>NOR</u> MAL Or ABNORMAL			1 js 2 M
Visible Emission From Shaker	Nor	the stable before the control of the		
Visible Emission From Discharge Conveyor System	Nor		-	

- Visible inspection must be performed during normal daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.